

# Oil Field Environmental Incident Summary

**Incident:** 20160218180217      **Date/Time of Notice:** 02/18/2016 18:02

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** FEDERAL 16-8H

**Field Name:** FOUR EYES

**Well File #:** 16036

**Date Incident:** 2/17/2016

**Time Incident:** 02:00

**Facility ID Number:**

**County:** BILLINGS

**Twp:** 143

**Rng:** 100

**Sec:** 8

**Qtr:** SE SE

**Location Description:**

**Submitted By:** Sarah Paycer

**Received By:**

**Contact Person:** Sarah Paycer  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Badlands Terrain

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	1.5	Barrels	3	barrels
<b>Brine</b>					0	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/25/2016

**Clean Up Concluded:** 2/22/2015

**Risk Evaluation:**

None Noted

**Areal Extent:**

5'x1000'

**Potential Environmental Impacts:**

None Noted

**Action Taken or Planned:**

Ensure all Whiting employees aware of proper lock out / tag out procedures.

**Wastes Disposal Location:** Approved Disposal Facilities

**Agencies Involved:**

**Updates**

---

**Date:** 2/19/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release did not remain on location. Further follow-up necessary.

---

**Date:** 3/2/2016    **Status:** Inspection

**Author:** Crowder, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On location 3/2/2016, at 10:18 a.m. Release was to the north off location, and the release flowed in ditch area to the SE. Booms were placed in multiple locations along spill path. I don't see any remaining impacts at this time. More follow-up needed in the spring.